

Issues

Estimated time: 0.0 Spent time: 0.0

| #    | Project | Status | Tracker | Subject                        | Updated             | Last updated by | Priority    |        | Author   | Assignee | Start date | Due date |
|------|---------|--------|---------|--------------------------------|---------------------|-----------------|-------------|--------|----------|----------|------------|----------|
| 2901 | BUG     | Close  |         | APK--- Kernel Used<br>RAM      | 07/25/2024 03:49 PM | FAE Guest       | B-Important | SW     | PM (Jim) | PM (Jim) | 03/16/2024 |          |
| 2899 | BUG     | Close  |         | Recovery                       | 03/27/2024 04:22 PM | PM (Jim)        | B-Important | SW     | PM (Jim) |          | 03/15/2024 |          |
| 2838 | BUG     | Close  | HW      | CC---GPIO                      | 03/18/2024 03:30 PM | PM (Jim)        | B-Important | SW     | PM (Jim) |          | 03/04/2024 |          |
| 2638 | BUG     | Close  | VE      | Ethernet<br>8111HThoughtput--- | 12/27/2024 08:51 PM | PM (Jim)        | B-Important | HW, SW | PM (Jim) | PM (Jim) | 12/08/2023 |          |
| 2588 | BUG     | Close  | VE      | x86 Android<br>8GB64GBSD       | 12/26/2023 03:57 PM | Anonymous       | A-Urgent    | SW     | PM (Jim) | PM (Jim) | 11/24/2023 |          |
| 2510 | BUG     | Close  | VE      | V1414                          | 12/26/2023 03:57 PM | Anonymous       | C-Normal    | SW     | PM (Jim) | PM (Jim) | 10/27/2023 |          |
| 1591 | BUG     | Close  | VE      | EXAR APKttyXRUSB               | 12/05/2023 04:38 PM | PM (Jim)        | D-Ignore    | SW     | PM (Jim) | PM (Jim) | 08/08/2022 |          |